

## Rear-view camera OBD-coder for Mercedes Audio15 unit

For connection of a rear-view camera on the Audio15 unit, it is necessary to enable the head-unit's rear-view camera input, which can be done with the OBDcoder.

### Delivery contents

*Take down the SW-version and  
HW-version of the interface boxes,  
and store this manual for support  
purposes.*

HW \_\_\_\_\_

SW \_\_\_\_\_



### Legal Information

Changes/updates of the vehicle's software can cause malfunctions of the interface. We offer free software-updates for our interfaces for one year after purchase. To receive a free update, the interface must be sent in at own cost. Labor cost for and other expenses involved with the software-updates will not be refunded.



**LED information:**

<b>LED</b>	<b>Status</b>	<b>Explication</b>
Green	Lights	Coding procedure successfully completed
	Flashes	Coding process is running
Red	Lights	Remove coding procedure successfully completed
	Flashes	Coding process failed / license violation
Green + Red	Lights	CAN Communication Error!- Abort of the diagnostic session